

## Damages' pricelist

No.	Damages' description	Unit	Quantity	Unit price (PLN)	MATERIAL / Services to be settled by purchase price
1	2	3	4	5	6
1	Door lock replacement	pc.	1	117,00	Door lock
2	Toilet door latch replacement	pc.	1	117,00	Toilet door latch
3	Door insert replacement, 'Yale' type	pc.	1	109,00	Door insert
4	Full panelled door leaves, single-parted, designed for internal entrance, max. 2,0 m2, factory-finished	pc.	1	101,00	Door leaf
5	Replacement of stoneware flooring, 1 m2	sqm.	1	646,00	Stoneware tiles
6	Replacement of stoneware plinths, 1 m long	m	1	131,00	Stoneware tiles
7	Replacement of floor stoneware tiles	tile	1	50,00	Stoneware tiles
8	Replacement of plinth stoneware tiles	tile	1	21,00	Stoneware tiles
9	Repairing damaged plastic floor	sqm.	1	105,00	Plastic carpeting
10	Replacement of glazed wall tiles, 30x30 cm	tile	1	63,00	Stoneware tiles / terracotta tiles
11	Plaster filling	sqm.	1	145,00	purchase of material at market prices to be added
12	Double coat of <b>emulsion paint on walls</b> , surface preparation included	sqm.	1	33,00	purchase of material at market prices to be added
13	Double coat of <b>emulsion paint on ceilings</b> , surface preparation included	sqm.	1	33,00	purchase of material at market prices to be added
14	Double coat of <b>oil-based paint on walls</b> , surface preparation included	sqm.	1	178,00	purchase of material at market prices to be added
15	Washbasin tap / sink tap replacement	pc.	1	208,00	Washbasin tap
16	Replacement of wall-mounted shower tap	pc.	1	254,00	wall-mounted shower mixer
17	Replacing a valve head, diameter 15-25 mm	pc.	1	70,00	Faucet head
18	Replacement of metal sink without supports	pc.	1	329,00	Sink
19	Replacement of ceramic washbasin	set	1	366,00	Washbasin
20	Replacement of ceramic toilet bowl, Compact type	set	1	1 361,00	Compact type bowl
21	Replacement of ceramic toilet bowl	pc.	1	406,00	Toilet bowl
22	Replacing a plastic toilet seat	pc.	1	66,00	Toilet seat
23	Replacement of ceramic urinal bowl	pc.	1	382,00	Urinal bowl
24	Replacing the heater valve	pc.	1	61,00	Heater valve with thermostatic head
25	Replacement of a sectional cast-iron heater	set	1	653,00	Cast-iron heater
26	Replacement of a steel double panel heater	set	1	378,00	Panel heater
27	Replacing power socket, up to 16A	pc.	1	49,00	Wall sockets (mechanism + frame)
28	Replacing a single-pole switch / button	pc.	1	59,00	Single-pole switches (mechanism + frame)
29	Replacing a series / staircase /cross-type / chandelier switch	pc.	1	72,00	Multipole switches (mechanism + frame)
30	Replacing fluorescent / LED luminaires	pc.	1	174,00	Fluorescent / LED luminaires
31	Replacing a broken fire detector	pc.	1	760,00	
32	Replacing a red manual alarm callpoint box	pc.	1	800,00	
33	Replacing a damaged windowsill	lin.m.	1	80,00	
34	Replacing a broken handle	pc.	1	35,00	
35	Duplicating a system door key	pc.	1	160,00	
36	Replacing a double-glazed unit	pc.	1	120,00	
37	Replacing a damaged window mechanism	pc.	1	400,00	
38	Replacement of damaged doors and doorframe	pc.	1	500,00	
39	Replacement of damaged fire doors to the room unit	pc.	1	950,00	
	<b>BEDCLOTHES</b>				
40	Pillow 70/80 cm	pc.	1	36,00	
41	Quilt 160/200 cm	pc.	1	60,00	
42	Blanket 120/200	pc.	1	50,00	
43	Quilt cover 160 /200 cm	pc.	1	55,00	
44	Pillow case 70/80 cm	pc.	1	15,00	
45	Bedsheet 140/200	pc.	1	26,00	
	<b>EQUIPMENT</b>				
46	Chair	pc.	1	120,00	
47	Table 80/80 cm	pc.	1	300,00	
48	Desk 70/50 cm	pc.	1	300,00	
49	Mattress 90 /200cm	pc.	1	200,00	
50	Big refrigerator	pc.	1	1 500,00	
51	Small refrigerator	pc.	1	700,00	
52	Vacuum cleaner	pc.	1	700,00	
	<b>SERVICES</b>				
53	Room cleaning	pc.	1	250,00	
54	Cleaning common areas (segment corridor, bathroom)	pc.	1	200,00	

Dormitory administrators are in charge of estimating the damage extent